Industrial Engineer

Devoted to the Maintenance and Operation of
Electrical and Associated Mechanical
Systems in Mills and Factories

Volume 80

January to December, 1922

UNIVERSITY OF MINNESOTA LIBRARY

McGRAW-HILL COMPANY, INC.
Old Colony Building
CHICAGO, ILLINOIS

UNIVERSITY OF
MINNESOTA
LIBRARY

FEB 17 '25

INDEX TO VOLUME 80

January to December, 1922

En620.5
fIn206

GENERAL INDEX

Pages by Months

January	1 to 56
February	57 to 104
March	105 to 155
April	157 to 208
May	209 to 262
June	263 to 314
July	315 to 362
August	363 to 410
September	411 to 460
October	461 to 508
November	509 to 558
December	559 to 608

A

Accident prevention (see Safety).
Acid-proof construction for conduit and lamps. By W. B. Todd, *38.
Air compressor (see Compressor).
Arc welding (see Welding).
Alarms (see also Signals).
——Circuit-breaker opening indicated by. By W. A. Oehlshlager, *138.
——Circuit condition indicated by ordinary bell. By C. C. Moller, *139.
——Fire, pilot lamp indicates which gong is ringing. By N. S. Davis, 242.
——Fire. By J. Elmer Housley, *382.
Annunciator for jig room of machine shop. By H. S. Rich, 399.
Answers to readers' problems (see Questions and answers).
Armatures:
——Baking out, reducing time for. By George Bender, 400.
——Banding, *503.
——Coils:
Direct-current, laying out. By A. C. Roe, *159.
Spreading device. By A. L. Gear, *248.
Threading cotton sleeving on. By L. E. Wood, *46.
Winding, to insure thorough impregnation. By A. C. Roe, 601.
——Drying out, when no oven is available. By Dexter W. Allis, *49.
——Repair work, varying lathe speed for, *199.
——Repairs in large steel mill reduced by contest. By D. W. Blakeslee, *97.
——Rotation reversal due to open and grounded field lead, repeated. By A. J. Dixon, *300.
——Shafts:
Broken, welded without removing coils. By L. I. Grinnell, 198.
Forcing on, device for. By James Dixon, *46.
Plugging small. By Eustace C. Soares, *49.
——Stand for holding, portable. By W. A. Harris, *95.
——Testing, for opens, shorts and grounds. By Ray C. Stanford, *452.
——Tools for repairing, *249.
——Winding:
Data sheet for winding and repair information, *305.
Direct-current, trouble in. By Marin Philips, *435.
Hand, saves time in rewinding small. By A. C. Roe, *502.
Work bench for, *453.
Ashes (see Handling materials).
Auto transformer (see Transformers).

B

Batteries, storage, systematic care. By Arthur F. Campbell, 95.
Bearings:
——Ball. By G. A. Van Brunt, *420.
——Ball thrust, reduces power consumption of pump motor. By H. E. Stafford, *397.
——Maintenance to prevent failure of motor service. By A. L. Gear, *265.
——Lubrication, *395.
——Oil escape from, prevented, *251.
——Oiling overhead, with oil can fastened on long handle. By Dexter W. Allis, *138.
——Roller, By G. A. Van Brunt, *420.
——Troubles, remedying. By W. B. Smith, 196.
Bell-ringing transformer (see Transformer).
Belts (see also Motor drive).
——Drive near wall, using. By H. S. Rich, *192.
——Static electricity on. By Leon L. Pollard, *448.
——Tightening short, on individual motor drives. By Alex. H. May, *88.
Blower, localized, improves working conditions. By J. S. Thomas, *199.
Boxes, outlet:
——Concrete columns, set in. By T. F. Dickman, *38.
——Concrete forms, side, fastened in. By Lyman L. Afton, *43.
Brushes:
——Carbon, diagnosing troubles. By E. H. Martindale, *475.
——Carbon, selecting proper grade of, 246.
——Contact, poor, seriously affects speed of d.c. motor. By J. M. Walsh, 200.
——Operation, faulty. By E. H. Martindale, *579.
Bulbs, incandescent lamp (see Lamps).
Butt welding (see Welding).

C

Cables:
——Clamp and tap-off made from same castings. By Charles E. Smith, *195.
——Conduit required for, determining size of. By W. S. Jones, *548.
——Dead-ending for heavy, inside factory, 353.
——Factory substation, steel messenger wire supports, *246, comment. By G. H. McKelway, 302.
——Flexible, used for crane power feeders, *242.
——Heating prevented, induction. By W. E. Seward, *243.
——Vertical, held taut by turnbuckles. By Raymond H. Weaver, *192.
Cement mills (see Mills, cement).
Chain drive (see Motor drive).
Charts (see Records).
Circuit breakers:
——Alarm attachment tells when circuit is opened. By J. M. Walsh, *37.
——Alarm indicates openit. of. By W. A. Oehlshlager, *138.
——Heating prevented, induction. By W. E. Seward, *243.
——Mounted on angle iron, oil. By F. W. McGraw, *140.
Cloth (see Handling materials).
Coal (see Handling materials).
Coils (see also Motor repair and rewinding):
——Armature:
Spreading, device for. By A. L. Gear, *248.
Threading cotton sleeving on. By L. E. Wood, *46.
Winding to insure thorough impregnation. By A. C. Roe, 601.
——Chuck for winding, in small speed lathe, *599.
——Cross-over, changed to one less liable to short-circuit. By A. C. Roe, *550.
——Diagrams for coil winders' record information. By A. C. Roe, *283.
——D. C. windings, cutting out coils in. By A. C. Roe, *384.
——Field coils of motors, transformer for testing. By A. E. Kirkly, *250.
——Field, testing for short circuits. By A. C. Roe, *549.
——Insulating, before they are placed in motor, block for. By L. E. Wood, *94.
——Insulation, varnishes for, 356.
——Low-resistance, tested with telephone receiver. By James Dixon, *47.
——Making. By A. C. Roe, *337.
——Reversed field, locating with a.c. By C. M. Hathaway, 501.
——Winding machine made from old lathe. By Ivan C. Wehnes, *549.
Communication (see Signals).
Commutators:
——Clamping ring, cutting mica right shape for insulating. By C. G. Pierce, *200.
——Fillers which may be used for plugging. By Henry Hazelton, 247.
——New machines, on. By James Dixon, 547.
——Throws, diagrams of, *355.
——Turning, *503.
Compensators:
——Limits heavy starting current of induction motor, automatic, *447.
——Mounted on ceilings. By H. L. Burns, *245.
——Mounted on strap iron support. By A. R. McDonald, *88.
——Reconnecting 110-volt for emergency use with 220-volt motor. By H. H. Lockyear, *247.
Compressor can be taken to the job, portable air. By W. H. Harold, *600.
Concrete wall removed by use of compressed-air driven paving breakers. By M. A. O'Brien, *546.
Conductors on steel members, supporting. By C. Walker, *38.
Conduit:
——Acid-proof construction. By W. B. Todd, *38.
——Coupling, steam flange union used as, in cramped space. By N. S. Davis, 195.
——Size of, for wires and cables. By W. S. Jones, *548.
——Uncoupling, emergency arrangement for. By Irving E. Sweazey, *39.
Control, motor (see Motor control).
Conveyors:
——Barrels handled from basement to box car by, *307.
——Packing and shipping department, in, *150.
——Pipe fittings handled by, in works of George B. Limbert Co., *571.
——Porcelain handled with, at Square D plant, *404.
——Portable, and sand loader, *252.
——Varnish, saves two-thirds of labor formerly required to load car of, *98.
——Water bottling plant, mineral, *505.
Cranes:
——Axle housings piled by lift truck with crane attachment, *553.
——Feeder in conduit. By H. S. Rich, 349.
——Gang replaced by magnet, one man and, *602.
——Inspector, things the, looks for. By A. L. Gear, *111.
——Locomotive:
Iron scrap handled by magnet and, *255.
Iron, with electro-magnet handles pig and scrap. By L. B. Horton, *98.
——Overhead:
Machine shop, in, *99.
Shops with low ceilings, installing in, *148.
——Pipe wrench on heavy work pulled by, *358.
——Power feeder, flexible cables used for, *242.
——Signal system to call operator. By A. L. Gear, *451.
——Rails, copper shoes prevent rust forming on. By H. S. Rich, *41.
——Runway conductors, structural steel shapes used as. By William Sheriff Jones, 598.
——Traveling, handles metal scrap, *552.
Cranes:
——Trolley quickly repaired by brazing. By Eustace C. Soares, *146.
——Truck speeds up changing of forging dies, *202.
Cross-over coil changed to one less liable to short circuit. By A. C. Roe, *550.
Cutter, porcelain tube, made from gas pliers. By H. S. Rich, *48.
Cutting heavy copper billets with electric arc. By A. M. Candy, *448.

D

Distribution in American Sugar Refining Co. By Roger B. Stevens, *463.
Drill stand for repair work, dual purpose bench, *303.
Drilling large holes in thin sheet steel, template for. By H. S. Rich, *354.
Drive, motor (see Motor drive).
Dynamometer for small motors. By John E. Snow, *499.

E

Editorials, 35, 84, 135, 188, 236, 294, 344, 390, 442, 492, 540, 590.
Electrical Review (see "Industrial Engineer").
Electrification of industrial works, *6, Comment, 35.
Electrodes (see Weldings).
Electromagnets (see Magnets, electric lifting).
Elevators:
——Braking on, squirrel-cage motor used for regenerative By H. T. Nafziger, *596.
——Door sill, automatic, speeds up handling trucks, *357.
——Pipe fittings plant of George B. Limbert Co., in *571.
——Portable, cuts labor in half in loading bagged material from cars, *147.
——Signals system enables one attendant to operate two, on holidays. By A. J. Dixon, *241.

F

Factor, power (see Power factor).
Failure, motor (see Motor failure).
Felt (see Handling materials).
Fiber, cutting, to narrow widths. By K. Knowles, *94.
Feeders, running heavy open wire, *88.
Filing (see Records).
Fire alarms (see Alarms).
Fire pumps, installing, By G. A. Van Brunt, *583.
Fixtures (see Lighting).
Frequency booster, slip-ring motor used as. By Philip G. Bernholz, 143.
Fuses:
——Mercury-arc rectifier, sizes for. By H. E. Weightman, 192.
——Motors, selecting size of fuses for. By L. W. Going, *416.
Furnaces, electric:
——Brass, improper electrodes in operatings. By James S. Brusster, 42.
——Enamel fusing, 54.
——Metal melting. By H. M. St. John, *17, Comment, 36.

G

Generators:
——Development of, *106.
——Direct-current, troubles. By H. E. Stafford, 430.
——Two-phase 2,200-volt, changed to operate at three-phase 220 volts. By A. C. Roe, *453.
Grid-resistor boxes supported by pipe framework, *595.
Grinders, surface, care of, *142.
Ground connections, size of wire to use for protective. By William S. Jones, 449.

H

Handling materials (see also Conveyors, Cranes, Hoists, Magnetic separators, Magnets, Tractors and Trucks):
——Ashes, dump body on truck for, *457.
——Awkward and heavy loads handled by electric industrial truck, *602.
——Axle housings, piling with electric lift truck having crane attachment, *553.
——Bag piler, portable, reduces six-men gang to two men, *203.
——Charging malleable furnaces, electric charger for, *359.
——Cloth, rolls of, at cutting table handled on special skid, *603.
——Coal:
Ashes and, dump body on truck for, *457.
Cost cut, *52.
Portable loader and industrial truck handle, *306.
——Dies, forging, *202.
——Felt rolls handled with one-man hoist. By Charle W. Geiger, *405.
——Five men to do material handling of eight-man gang, getting, 553.
——Intra-plant transportation, electric-truck. By J. Elmer Housley, *325.
——Iron:
Pig and scrap, handled by locomotive crane with electromagnet. By L. B. Horton, *98.
Reclaiming, magnetic separator for, *506.
Scrap, handled by magnet and locomotive crane, *255.
——Loose material, steel dump-body skids for, *358.

*Indicates illustrated articles

330124

FEB 17 '25

Handling materials:
——Lumber, handling large quantities at low cost, *53.
——Magnetic separator for reclaiming iron, *506.
——Metal scrap, traveling crane and magnet for, *552.
——Oliver Chilled Plow Works, moving 300 tons of material daily at, *185.
——Paper and felt rolls with one-man hoist. By Chas. W. Geiger, *405.
——Piler, portable bag, reduces six-men gang to two men, *203.
——Piling and tiering machines with telescoping frame, *456.
——Pipe fittings in works of George B. Limbert Co., *571.
——Plant production organized around material-handling plan, *59.
——Porcelain with conveyors at Square D plant, *404.
——Posts, steel, handled on lift trunk with stationary skid supports, *552.
——Sand, loader and portable conveyor save half the cost of handling, *252.
——Scrap:
Handling, *254.
Iron, handled by magnet and locomotive crane, *255.
Iron, handled by locomotive crane with electro-magnet. By L. B. Horton, *98.
Metal, handled by traveling crane and magnet, *552.
——Steel, fifteen-foot, handled on special lift truck, *259.
——Tiering and piling machines with telescoping frame, *456.
——Water bottling plant, conveyor system of mineral, *505.
——Wire and wire rod, *403.
——Wire, using combination of lift truck and monorail to handle heavy rolls of, *253.
Heaters, electric, cork composition softened and uniform temperature maintained by. By Albert Kochs, *139.
Hiring and firing. By Practical Pete, *105.
Hoists:
——Beats hand crane by $7,000 per year, *51.
——Labor and floor-space saved by, *100.
——Paper and felt rolls handled with one-man. By Charles W. Geiger, *405.
——Remote control of motors on. By Eustace C. Soares, *99.
——Steel warehouse, two men do four men's work in, with aid of, *202.

I

Ice machine converted to electric drive at small cost. By W. C. Heston, *39.
Incandescent lamps (see Lamps).
"Industrial Engineer":
——Field served by, *2.
——Editorial plan and its scope, 4.
——Name, concerning our. By Daniel H. Braymer, 345.
Industrial Engineers (see Society of Industrial Engineers).
Inspection and maintenance (see also Testing).
——Brushes, carbon. By E. H. martindale, *475.
——Cement-mill motors, *169, Comment, 188.
——Commutators on new machines. By James Dixon, 547.
——Direct-current motor troubles. By H. E. Stafford, 430.
——Dusty factories, small motors driving machines in. By H. E. Ewalt, *289.
——Induction-motor troubles—diagnosis and remedies. By H. E. Stafford, 22, 336.
——Instruments for. By J. M. Walsh, *479.
——Large industrial plant methods. By I. H. Gaskin, 44.
——Motors in steamy and wet places. By Norman B. Smith, *515.
——Motors, 1,200 kept running. By H. E. Wood, 546.
——Records, clear-cut equipment, facilitate, *50.
——Reports insure prompt action. By A. G. Humphrey, *47.
——Split-phase windings, locating troubles in. By A. C. Roe, *229.
——Squirrel-cage motor rotor, test for defective. By Philip G. Bernholz, 42.
——Steel and tube mill. By Arthur J. Whitcomb, *23.
——Swift & Company's motors. By Norman B. Smith, *515.
——Switches, safety. By R. B. Anderson, *527.
——Synchronous motor troubles. By H. E. Stafford, 217.
——Trucks, industrial. John Causland, *27.
——Western Clock Company. By L. J. Stewart, *317.
Installation, motor (see Motor installation and mounting).
Instruments (see also Meters):
——Electrical, care of. By John H. Miller, 92.
——Maintenance work, for. By J. M. Walsh, *479.
Insulation:
——Cabinet for storing, repair man's *197.
——Cell bender for forming slot. By A. C. Roe, *251.
——Coil, varnishes for, 356.
——Properties, desirable, 48.
——Resistance, testing (editorial comment), 344.
——Trimmer for cutting strips. By J. M. Walsh, *249.
Insulator base, wall-mounted, converted into pipe-mounted type. By Frank Harazim, *40.
Insurance protection from loss by breakdown of electrical equipment. By B. K. Spencer, *486.
Iron (see Handling material).

J

Jackshaft, emergency repair of broken. By A. J. Dixon, *599.

L

Laminations, angle iron clamp for restacking. By L. E. Wood, *48.
Lamps, electric (see also Lighting).
——Acid-proof construction. By W. B. Todd, *38.
——Burnouts by high voltage prevented by balance control set. By J. M. Walsh, *41.
——Cleaning (editorial), 590.
——Enameled, handling, 38.
——Guard bar holds lamp in place. By John W. Pearson, *497.
Lamps:
——History, *58, Comment' 85.
——Life of, in a.c. and d.c. service (editorial), 492.
——Life of type C Mazda. By D. W. Blakeslee, *352.
——Pilot, indicates which gong of fire alarm system is ringing. By N. S. Davis, 242.
——Pilot, in motor circuit near starter tells whether motor is running. By N. S. Davis, 138.
——Portable storage-battery, for very damp locations, *42.
——Type C Mazda, life of. By D. W. Blakeslee, *352.
Lighting (see also Lamps).
——Benches and lathes, adjustable lights for. By J. H. Gallant, *497.
——Bracket for close work, swinging. By R. S. Lowry, *396.
——Brackets for factory roadway, standardized, *351.
——Fixture, adjustable industrial, *301.
——Foundry. By J. M. Shute, *165.
——Problems, graphic solution of. By C. W. Kinney, *244.
——Record blank useful in illumination surveys, *596.
——Reflector mounted out of way of traveling crane. By Samuel G. Hibben, *139.
——Wastage of light. By Ward Harrison and J. R. Colville, *13, Comment, 36.
——Woodworking plants. By A. D. Bell, *511.
Load survey shows whether proper size motor is being used. By Herbert J. Wolfe, 195.
Lubrication (see Bearings).
Lumber (see Handling materials).

M

Machine tools, motor drive. By Robert Harris, *365.
Magnets:
——Control, broken short-circuiting rings cause of trouble in. By J. J. Luchessa, 298.
——Gang replaced by one man, crane and, *602.
——Iron scrap handled by, and locomotive crane, *255.
——Lifting, soon pay for themselves, work where, *54.
——Locomotive crane with, handles pig and scrap iron cheaply. By L. B. Horton, *98.
——Metal scrap, handling, *552.
Magnetic:
——Clutch connects main flour mill drive to motor. By F. R. Lufkin, *37.
——Separator for reclaiming iron, *506.
Maintenance (see Inspection and maintenance).
Material handling (see Handling material.)
Measurements (see Instruments and meters.)
Meters (see also Instruments).
——Indicating, history, *264.
——Integrating, history, *316.
——Portable, care of. By Dexter W. Allis, 449.
——Watt-hour, necessity for reading daily, 40.
Mills:
——Cement, motor inspection in, *169, comment, 188.
——Cotton, Riverside and Dan River, *70, correction, 155.
——Steel:
Inspection and maintenance in tube and. By Arthur J. Whitcomb, *23.
Motor failures. By Arthur J. Whitcomb, *377.
Reversing roll electric drives, trouble in. By Arthur J. Whitcomb, *63.
Motor bearings (see Bearings, motor).
Motor control:
——American Sugar Refining Co. By Roger B. Stevens, *463.
——Bag piler, portable, *399.
——Compensators:
Limits heavy starting current of induction motor, automatic, *447.
Mounted on ceilings. By H. L. Burns, *245.
Mounted on strap iron support. By A. R. McDonald, *88.
Reconnecting 110-volt, for emergency use with 220-volt motor. By H. M. Lockyer, *247.
——Central, why adopt. By Orville F. Long, *180.
——Installing. By Herbert Harries, *433.
——Machine tools. By Robert Harris, *365.
——Shaper, motor-starting switch mounted at rear of motor-driven. By F. W. McGraw, *450.
——Starters:
Alternating current, history, *510.
Direct current, development, *412.
Troubles—diagnosis and remedies. By H. E. Stafford, 336.
——Starting motor when line voltage is often low. By Jan A. Vanderpoll, *545.
——Stop control put within reach of three men on automatic machine, *547.
——Switches, safety, use and maintenance. By R. B. Anderson, *527.
Motor drive (see also Belts and Pulleys).
——Chain eliminates trouble of belt drive on short centers. By Thomas Hafziger, 350.
——Chain, on stock calendar, *351.
——Direct, for capping machines saved aisle space, *301.
——Individual, on special machines, installing. By James W. Carpenter, *597.
——Portland (Maine) railroad shops, revamped, in, *282.
Motor failures:
——Editorial, 591.
——Steel-mill. By Arthur J. Whitcomb, *377.
Motor-generator set starting trouble, increasing air gap removes. By J. E. Housley, 305.
Motor inspection (see Inspection and maintenance).
Motor installation and mounting.
——Beams, on wood and iron, *40.
——Ceiling I-beam, clamp for supporting motor from. By A. R. McDonald, *196.
——Ceiling of reinforced concrete building, motors and starters on. By F. W. McGraw, *194.
——Columns, structural steel bracket for mounting motors on. By C. A. Donaldson, *141.
——Examples of, *20.
——Foundations, T-square used to line up. By J. Jensen, *300.
——Housing protects against dust and gases. By H. E. Stafford, *395.
——Ideas on, let's have your (editorial), 189.
——Identification and location in Crane Company, *330.
——Increasing speed and safety when installing heavy equipment overhead, *241.
——Inside of machine saves aisle space, *299.
Motor installation and mounting:
——Keystone Spring Works. By T. W. C. Hartmann, *227.
——Machine tools. By Robert Harris, *365.
——Pipe-support for screw machine motor, *399.
——Platform for suspending near ceiling. By H. S. Rich, *498.
——Protected, speeds up production. By T. W. C. Hartmann, *227.
——Scaffold, knockdown, for, *343.
——Shifting, *194.
——Small A. C. motor mounted so that it will not hum. By Dexter W. Allis, *196.
——Structural steel in mounting motors on machines. By A. S. Mill, *119.
——Temporary drive, *41.
——Thousand-pound motor suspended near ceiling by simple rigging. By H. S. Rich, *240.
Motor maintenance (see Inspection and maintenance).
Motor mounting (see Motor installation and mounting).
Motor panels (see Panels, motor).
Motor repair and rewinding (see also Coils and Tools):
——Armatures:
Baking out, reducing time for. By George Bender, 400.
Banding, *503.
Coil, insuring thorough impregnation of. By A. C. Roe, 601.
Coil spreading device. By A. L. Gear, *248.
Coils, threading cotton sleeving on. By L. E. Wood, *46.
Contest in large steel mill reduces repairs. By D. W. Blakeslee, *97.
Data sheet for winding and repair information, *305.
D. C., laying out coils for. By A. C. Roe, *159.
Direct-current, troubles in winding. By Marin Phillips, *435.
Drying out, when no oven is available. By Dexter W. Allis, *49.
Lathe speed for, varying, *199.
Rewinding small, hand winding saves time in. By A. C. Roe, *502.
Shafts, broken, welded without removing coils. By L. I. Grinnell, 198.
Shafts, device for forcing on. By James Dixon, *46.
Shafts, plugging small. By Eustace C. Soares, *49.
Split and layer windings for small. By A. C. Roe, *78.
Stand for holding, portable. By W. A. Harris, *95.
Ten men in one month re-wind 2,000, p. *120.
Tools for, *249.
Work bench for winding, *453.
——Brushes:
Operation, faulty. By E. H. Martindale, *579.
Troubles, diagnosing. By E. H. Martindale, *475.
——Coil and commutator throws, diagrams of, *355.
——Coil-making methods. By A. C. Roe, *337.
——Coils for D. C. armatures and A. C. stators, laying out. By A. C. Roe, *159.
——Commutators:
Clamping ring, cutting mica right shape for insulating. By C. G. Pierce, *200.
Fillers which may be used for plugging. By Henry Hazelton, 247.
New machines, on. By James Dixon, 547.
Throws, diagrams of, *355.
Turning, *503.
——Data which should be kept when motors are rewound. By W. R. Gibson, 354.
——Direct current troubles. By H. E. Stafford, 430.
——Direct current windings, cutting out, coils in. By A. C. Roe, *384.
——Fractional horsepower D. C. By A. C. Roe, *7.
——Induction:
Diagram of connections of. By R. McDonald, *501.
Prices for rewinding, checking repair-shop, *67.
Rotors of old style, welded by oxyacetylene torch, *304.
Troubles—diagnosis and remedies. By H. E. Stafford, 22, 336.
——Prices for rewinding induction motors, how to check repair-shop, *67.
——Reconnecting, to reduce speed from 1,200 R.P.M. to 900 R.P.M. By H. E. Stafford, *400.
——Rotation of motor-driven machine, reversing. By F. W. McGraw, *398.
——Rotor connections, wound. By A. C. Roe, *533.
——Rotors, squirrel-cage, arc welded. By A. M. Candy, *400.
——Scafford for, knockdown, *343.
——Shaft sleeve to renew wearing section, seamless steel tube used as, *452.
——Small motors, winding. By A. C. Roe, *481.
——Stator holder for motor-winding shop, *93.
——Swift & Company. By Norman B. Smith, *515.
——Trouble wagon, *89.
——Troubles—diagnosis and remedies. By H. E. Stafford, 336.
——Two-phase reconnected for three-phase operation. By C. A. Johnson, 93.
——Two-phase, rewound for three-phase operation. By A. C. Roe, 144.
——Three-phase operation, two-phase motor reconnected for. By C. A. Johnson, 93.
——Three-phase operation, two-phase motor rewound for. By A. C. Roe, 144.
——Universal, By A. C. Roe, *568.
——Voltage, changing. By C. A. Johnson, *401.
——Wagon, trouble, *89.
Motor rewinding (see Motor repair and rewinding).
Motor starters (see Motor control).
Motor testing (see Testing).
Motor troubles (see Inspection and maintenance, Motor failure and motor repair and rewinding).
Motors, electric (see also Motor control, Motor drive, Motor failure, Motor installation and mounting, Motor repair and rewinding and Inspection and maintenance.)
——History, 158.
——Load survey shows whether proper size is being used. By Herbert J. Wolfe, 195.
——Old timers, *461, *509.
Mounting, motor (see Motor installation and mounting).

N

National Safety Congress (editorial), 345.

O

Oiling and oils (see Bearings).
Organization plan that inspires initiative and responsibility. By J. Helmer Housley, *131, comment, 105.
Outlet boxes (see Boxes).
Ovens, electric. By Wirt S. Scott, *275.

P

Panelboard, two-wire distribution easily changed to three-wire. By William S. Jones, *193.
Panels, motor service, made with standardized equipment. By C. H. Matthews, *271.
Paper (see Handling materials).
Paving breakers used to remove concrete wall. By M. A. O'Brien, *546.
Pete, Practical (see Authors' Index).
Phase rotation, rewound motor for testing. By A. C. Roe, 93.
Pig iron (see Handling material, iron).
Piling (see Handling materials).
Pilot lamp (see Lamps).
Pipe:
——Coupling bent, in out-of-the-way corners. By Frank Harazim, *299.
——Coupling bent, in out-of-way places. By G. S. Rolf, 451.
——Fittings, forty-five degree, save time on installation job, *298.
Pitch applied to shoe parts by electrically-operated machine. By Albert Kochs, *240.
Plug and plug-board designed for hard service. By L. C. Beaty, *49.
Polarity of commutating poles, inductive test for. By M. J. Rich, *96.
Porcelain (see Handling material).
Posts (see Handling materials).
Power factor, correcting. By E. H. Hubert, *561.
Practical Pete (see Authors' Index).
Prices for rewinding induction motors, how to check repair shop, *67.
Protection (see also Insurance).
——American Sugar Refining Co. By Roger B. Stevens, *463.
——(Practical Pete), *315.
Pulleys (see also Motor Drive).
——Creeping on motor shaft, preventing. By A. J. Dixon, *595.
——Rack for storing spare. By H. S. Rich, *304.
——Service and long life. By Frank E. Gooding, *575.
——Size simplification, motor (editorial), 344.
——Sizes and types, pointers on. By Frank E. Gooding, *519.
——Speed, changing slightly. By H. S. Rich, *199.
Pumps, fire, installing. By G. A. Van Brunt, *583.
Purchasing:
——Ordering electrical supplies, *214.
——Western Clock Company. By L. J. Stewart, *317.

Q

Questions and Answers, 238, 296, *346, 392, *444, *494, *542, *592.

R

Records:
——Armature winding and repair information, data sheet for, *305.
——Chart tells where troublemen are, *50.
——Coil and commutator throws, diagram of, *355.
——Coil winders' record information, diagrams for. By A. C. Roe, *283.
——Data which should be kept when motors are rewound. By W. R. Gibson, 354.
——Equipment and inspection, *211.
——Equipment, clear-cut, facilitate maintenance, *50.
——Illumination surveys, blank for, *596.
——Inspection reports insure prompt action. By A. G. Humphrey, *47.
——Motor-drive information, how to file. By L. S. Lincoln, 76.
——Western Clock Company. By L. J. Stewart, *317.
Reflectors (see Lighting).
Repairs (see Motor repairs and rewinding).
Review, Electrical (see "Industrial Engineer").
Rewinding (see Motor repair and rewinding).
Rheostat:
——Lighting circuit used as, for speed control on special work. By Dexter W. Allis, *350.
——Mounted on frame of boring mill, adjustable speed control, *349.
Risers in buildings, supporting varnished, cambric, insulated. By F. A. Westbrook, *351.
Rotors (see Motors repairs and rewinding).

S

Safety (see also National Safety Congress):
——Motor equipment menaced by lax installation methods, *302.
——Switches, precautions when opening high-tension. By H. S. Rich, 141.
——Welding, rules for arc. By D. N. Louis, 245.
Safety switches (see Motor control and switches).
Sand (see Handling materials).
Saw, pull-out force determines right motor size for, 90.
Scaffold made from two ladders, portable. By J. B. Rakoske, *349.
Scrap (see Handling material).
Screw-driver (see Tools).
Separators (see Magnetic separator).
Service sectionalized at stairway landings, 40.
Signals:
——Annunciator for jig room of machine shop. By H. S. Rich, 399.
——Bridgeport, (Conn.) Brass Company plants, *107.
——Cooling-tower sump, covered lights show high and low stage of water in. By A. J. Dixon, *498.
——Crane operator, to call. By A. L. Gear, *451.
——Elevator, system enables one attendant to operate two on holidays. By A. J. Dixon, *241.
Slate, making, speed in drilling. By H. S. Rich, *145.
Slotting machine for undercutting mica on commutators. By R. H. H. Lockyer, *201.
Society of Industrial Engineers. By Frank E. Gooding, 261, 493.
Soldering:
——Electrical equipment. By James Dixon, 551
——Pot for induction—motor rotors. By R. H. H. Lockyer, *247.
——Rotor, outfit made of pipe fittings. By Stephen Tillman, *146.
Spot welding (see Welding).
Starters, motor (see Motor control).
Stator (see Motor repair and rewinding).
Steel (see Handling material).
Steel mills (see Mills).
Stockkeeping:
——Responsibilities of the electrical stockkeeper. By Arthur A. Barbera, *31.
——Western Clock Company. By L. J. Stewart, *317.
Storage batteries (see Batteries, storage).
Swift & Company's motors. By Norman B. Smith, *515.
Switchboards:
——Cables, grouping, 43.
——Development, *462.
——Frames kept from heating. By W. E. Seward, *142.
——Lighted by lamps on ceiling. By D. W. Blakeslee, *92.
——Lighting—feeder, safety. By F. W. McGraw, *91.
——Safety and flexibility for extensions combined. By V. K. Stalford, *353.
Switches:
——Centrifugal, strong spring on, burns out motor winding. By P. Justus, *601.
——Disconnecting, history, *364.
——Door, swinging—adapted to sliding. By Clayton J. Demeritt, *193.
——High-tension, safety precautions when opening. By H. S. Rich, 141.
——Knife, testing contact of blades. By H. J. Wade, 40.
——Mounting any size, using standard cast-iron insert. By Frank Harazim, *398.
——Starting, mounting four on one column, *90.
——Safety:
Enclosed, proper operation of. By J. E. Housley, 500.
Use and maintenance. By R. B. Anderson, *527.
Switching system for carrying lighting load from alternating or direct current service. By Walter L. Hamilton, *242.

T

Table, testing (see Testing).
Tape, rubber, way to keep it from sticking to connectors. By N. S. Davis, 140.
Telephone instrument development, *560.
Tension block that will not injure insulation on magnet wire. By J. M. Walsh, *197.
Testing:
——Armatures for opens, shorts and grounds. By Ray C. Stanford, *452.
——Board for two-phase, three-phase or direct current motors. By Eustace C. Soares, *97.
——Coils:
Field, for short circuits. By A. C. Roe, *549.
Field, of motors, transformer for. By A. E. Kirkly, *250.
Low-resistance, with telephone receiver. By James Dixon, *47.
——Heating units, ammeter plug box speeds up. By W. H. Farr, *303.
——Insulation resistance (editorial), 344.
——Lineshaft (editorial), 493.
——Motor repair work, test line for use in, *144.
——Phase rotation, rewound motor for testing. By A. C. Roe, *93.
——Polarity of commutating poles, inductive test for. By M. J. Rich, *96.
——Squirrel-cage rotor, defective. By Philip G. Bernholz, 42.
——Table, portable. By I. H. Gaskin, *47.
Textile mills (see Mills).
Tiering (see Handling materials and Trucks).
Tools:
——Armature-repair, *249.
——Bench drill stand for repair work, *303.
——Box, portable tool. By N. S. Davis, *187.
——Cutter, porcelain-tube, made from gas pliers. By H. S. Rich, *48.
——Home-made, for electrical repair shops, *94.
——Insulation trimmer for cutting strips. By J. M. Walsh, *249.
——Pack wires in partly closed slots, to. By A. C. Roe, *143.
——Resistance units for crane motor control rheostats wound by special. By A. L. Gear, *198.
——Screw drivers for small repair work, magnetos and split-blade, *200.
——Screw driver, motor driven, increases output 400 per cent, *146.
——Slot wedges into places, device to drive, *145.
——Undercutting, made from file and hacksaw blades, *44.
Torque, determining motor-starting, *96.
Tractors, electric industrial (see also Trucks).
——Heavy loads handled by battery-driven, *149.
——Maintenance. By John Causland, *27.
——Pier, saves 50 per cent at unloading, 51.
Trade literature, 55, 103, 154, 208, 262, 313, 361, 410, 460, 508, 558, 608.
Transformers:
——Auto:
Connected in parallel with one secondary switch. By Eustace C. Soares, *141.
Higher voltage from old compensator used as. By J. H. Gallant, *43.
——Bell-ringing, made from coil of old arc lamp. By N. S. Davis, *145.
——History, *210.
——Motor troubles, for locating. By C. A. Johnson, *45.
——Testing field coils of motors, for. By A. E. Kirkly, *250.
Transportation (see Handling materials, Tractors, Trucks).
Trolleys and runway, serviceable. By Walter H. Millman, *50.
Troubles, motor (see Inspection and maintenance, Motor failure and Motor repair and rewinding).
Trucks, industrial:
——Ashes, dump body for, *457.
——Awkward and heavy loads handled by electric, *602.
——Coal handled by, and portable loader, *306.
——Dump body on, for ashes, *457.
——Elevating platform, handling two-ton loads on, *204
——Elevator door sill, automatic, speeds up handling, *357.
——15-ton load handled by electric, *604.
——Handle with wheel and hook used to move two-wheeled, *148.
——Intra-plant transportation by electric. By J. Elmer Housley, *325.
——Lift:
Axle housings piled by, with crane attachment, *553.
Car unloading speeded up with, 554.
Skid for handling rolls of cloth at cutting table, *603.
Steel, fifteen-foot, handled by, *255.
——Maintenance. By John Causland *27.
——Miscellaneous handling, $1,200 a year saved, *603.
——Pipe fittings handled by, in works of George B. Limbert Co., *571.
——Posts, steel, handled on lift truck with stationary skid supports, *552.
——Preliminary investigations on electric, By D. Wright, 455, 456.
——Red light in aisles calls operators, 308.
——Rollways, permanent on four-wheeled, *504.
——Safety switches stop joy ridings. By F. W. McGraw, *396.
——Tier-lift, facilitates loading cars from ground, *307.
Turnbuckles to tighten wires, substitutes for. By H. S. Rich, *500.

U

Undercutting tools made from file and hacksaw blades *44.
Underground installation, rubbered-covered wire and conduit save cost in. By H. B. Sherwood, *298.

V

Varnishes:
——Air-drying, insulating, 44.
——Coil insulation, for, 356.
Vehicles, electric (see Tractors and Trucks).
Ventilation of industrial works. By Frank E. Gooding, *369, editorial, comment, 390, correction, 371, comment, 597.

W

Water-level control, electrical. By M. M. Brown, *39.
Water, mineral (see Handling material).
Welding, electric:
——Arc:
Current should be proportional to thickness of metal welded. By D. M. Louis, 354.
Electrode, flat. By W. W. Palmer, *356.
Electrode size affects deposition of metal. By D. N. Louis, 303.
Safety rules for. By D. N. Louis, 245.
Squirrel-cage rotors. By A. M. Candy, *400.
——Armature shafts, broken, welded without removing coils. By L. I. Grinnell, 198.
——Butt—steel and iron pipe, energy requirements. By G. T. Jacocks, 89.
——Iron and steel. By E. Wanamaker, *218, Comment 238.
——Joining, seams by. By Practical Pete, *559.
——Operating radius of outfit increased by army searchlight reel. By Robert Harris, 601.
——Rock Island lines, reasons for success in shops of. By E. Wanamaker, *172.
——Spot, semi-automatic at E. N. Garrison Mfg. Co. By E. H. Hubert, *413.
Winding (see Motor repair and rewinding).
Wire (see also Wiring and Handling materials):
—— Conduit required for, determining size of. By W. S. Jones, *548.
——Lead-covered, best for wet, salty atmosphere. By F. A. Westbrook, 397.
——Rack for small reels maintains proper wire tension. By A. C. Roe, *355.
Wiring (see also Wire):
——Motor circuits, data for direct and alternating current, 178.
——Motor installation, data for. By H. L. Cornelison, *127.
——Safety and economy in. By H. S. Rich, 352.
——Sloppy job is an eye sore. By H. S. Rich, *243.
——Supports for light and power, on angle irons. By H. S. Rich, *193.
Woodworking plants, lighting in. By A. D. Bell, *51

*Indicates illustrated articles

AUTHOR INDEX

AFTON, LYMAN L. Side outlets fastened in concrete forms, *43.
Allis, Dexter W. Caring for portable meters, 449.
——Drying out armature when no oven is available, *49.
——Lighting circuit used as rheostat for speed control on special work, *350.
——Oiling overhead bearings with oil can fastened on long handle, *138.
——Small A. C. motor mounted so that it will not hum, *196.
Anderson, R. B. Use and maintenance of safety switches, *527.

BARBERA, ARTHUR A. Responsibilities of electrical stockkeeper, *31.
Beaty, L. C. Cheaply built plug and plug-board designed for hard service, *49.
Bell, A. D. Lighting in woodworking plants, *511.
Bender, George. Reducing time for baking out armature, 400.
Bernholz, Philip G. Slip ring motor used as frequency booster. 143.
——Test for defective squirrel-cage rotor, 42.
Blakeslee, D. W. Contest reduces armature repairs in large steel mill, *97.
——Lamps on ceiling light switchboard, *92.
——Type C mazda lamps have long life, *352.
Brown, M. M. Electrical control for water level, *39.
Brusster, James S. Improper electrodes in operating brass furnaces, 42.
Burns, H. L. Mounting compensators on ceilings, *245.

CAMPBELL, ARTHUR F. Systematic care of storage batteries, 95.
Candy, A. M. Arc welding squirrel-cage rotors, *400.
——Cutting heavy copper billets with electric arc, *448.
Carpenter, James W. Overcoming difficulties in installing individual drives on special machines, *597.
Causland, John. Maintenance of industrial trucks, *27.
Colville, J. R. (See Ward Harrison.)
Cornelison, H. L. Wiring data for motor installation *127.

DAVIS, N. S. Bell ringing transformer made from coil of old arc lamp, *145.
——Pilot lamp indicates which gong in fire alarm system is ringing, 242.
——Pilot lamp in motor circuit near starter tells whether motor is running, 138.
——Steam flange union used as conduit coupling in cramped space, 195.
——Tool box saves many trips, *187.
——Way to keep rubber tape from sticking to connectors, 140.
Demeritt, Clayton, J. Adapting swinging-door lamp switch to sliding door, *193.
Dickman, T. F. Setting outlet boxes in concrete columns, *38.
Dixon, A. J. Emergency repair of broken jackshaft, *599.
——Preventing creeping of pulley on a motor shaft, *595.
——Repeated reversals of armature rotation due to open and grounded field lead, *300.
——Signal shows high and low stage of water in cooling-tower sump, *498.
——Signal system enables one attendant to operate two elevators on holidays, *241.
Dixon, James. Screw device for forcing armature on shaft, *46.
——Soldering electrical equipment, 551.
——Testing low-resistance coils with telephone receiver, *47.
Donaldson, C. A. Structural steel bracket for mounting motors on columns, *141.

EWALT, H. E. Small motors that drive machines in dusty factories, *289.

FARR, W. H. Ammeter plug box speeds up testing of heating units, *303.

GALLANT, J. H. Adjustable lights for benches and lathes, *497.
——Higher voltage from old compensator used as auto transformer, *43.
Gaskin, I. H. Large industrial plant maintenance methods, 44.
——Portable testing table, *47.
Gear, A. L. Pointers on bearings help prevent failures of motor service, *265.
——Signal system used to call crane operator, *451.
——Special tool winds resistance units for crane motor control rheostats, *198.
——Spreading armature coils, *248.
——Things the crane inspector looks for, *111.
Geiger, Charles W. One-man hoist increases paper storage capacity, *405.
Gibson, W. R. Data which should be kept when motors are rewound, 354.
Going, L. W. Selecting size of fuses for motors, *416.
Gooding, Frank E. Management that includes bosses in the office and in the shop, 260.
——Pointers on sizes and types of pulleys, *519.
——Pulley service and long life, *575.
——Ventilation in industrial works, *369, comment, 390, connection, 485.
Grinnell, L. I. Broken armature shaft welded without removing coils, 198.

HAMILTON, WALTER L. Switching system for carrying lighting load from alternating or direct current service, *242.
Harazim, Frank. Coupling bent pipes in out-of-the-way corners, *299.
——Standard cast-iron insert for mounting any size switch, *398.
——Wall-mounted insulator base readily converted into pipe-mounted type, *40.
Harold, W. H. Portable air compressor can be taken to the job, *600.
Harries, Herbert. Installing motor control, *433.
Harris, Robert. Army searchlight reel increases operating radius of welding outfit, 601.
——Power service on machine tools, *365.
Harris, W. S. Portable stand for armatures, *95.
Harrison, Ward, and J. R. Colville. Reducing wastage of light, *13, comment, 36.
Hartmann, T. W. C. Protected motor service speeds up production, *227.
Hathaway, C. M. Locating reversed field coils with A. C., 501.
Hazleton, Henry. Fillers which may be used for plugging commutators, 247.
Heston, W. C. Ice machine converted to electric drive at small cost, *39.
Hibben, Samuel G. Lighting reflector mounted out of way of traveling crane, *139.
Horton, L. B. Locomotive crane with electromagnet handles pig and scrapiron cheaply, *98.
Housley, J. Elmer. Fire alarm systems, *382.
——Increasing air gap removed starting trouble with motor-generator set, 305.
——Intra-plant transportation of materials, *325.
——Organization plan inspires initiative and responsibility, 131, comment 105.
——Proper operation of enclosed safety switches, 501.
Hubert, E. H. Correcting power factor, *561.
——High-speed welding of small parts, *413.
Humphrey, A. G. Inspection reports insure prompt action, *47.

JACOCKS, G. T. Energy requirements in butt-welding steel and iron pipe, 89.
Jensen, J. T-square used to line up motor foundations, *300.
Johnson, C. A. Changing voltage of direct-current motor, *401.
——Device to drive slot wedges in place, *145.
——Reconnecting two-phase motor for three-phase operation 93.
——Transformer for locating motor troubles, *45.
Jones, William S. Panel board easily changed from two-wire to three-wire distribution, *193.
——Size of wire to use for protective ground connections, 449.
——Structural steel shapes used as crane runway conductors, 598.
Justus, P. Strong spring on centrifugal switch burns out motor winding, *601.

KINNEY, C. W. Graphic solution of lighting problems, *244.
Kirkly, A. E. Transformer for testing field coils of motors, *250.
Knowles, K. Cutting fiver to narrow widths, *94.
Kochs, Albert. Electric heater softens cork composition and maintains uniform temperature, *139.
——Pitch applied to shoe parts by electrically-operated machine, *240.

LINCOLN, E. S. Filing motor-drive information, 76.
Lockyear, H. H. Reconnecting 110-volt compensator for emergency use with 220-volt motor, *247.
Lockyer, R. H. N. Slotting machine for undercutting mica on commutators, *201.
——Special pot for soldering induction—motor rotors, *247.
Long, Orville F. Central control of motors, *180.
Louis, D. N. Nine safety rules for operating arc-welding sets, 245.
——Size of electrodes affects deposition of metal in arc-welding, 303.
——Welding current should be proportional to thickness of metal welded, 354.
Lowry, R. S. Swinging bracket light, *396.
Luchessa, J. J. Broken short circuiting ring cause of trouble in control magnets, 298.
Lufkin, F. R. Magnetic clutch connects main floor mill drive to motor, *57.

MARTINDALE, E. H. Diagnosing brush troubles *475.
——Faulty brush operation, *579.
Matthews, C. H. Motor service panels made up with standardized equipment, *271.
May, Alex. H. Tightening short belts on individual motor drives, *88.
McDonald, A. R. Clamp for supporting motor from ceiling I-beam, *196.
——Compensator mounted on strap iron support, *88.
McDonald, R. Diagram of motor connections, *501.
McGraw, F. W. Motor-starting switch mounted at rear of motor-driven shaper, *450.
——Mounting motors and starters on ceiling of reinforced concrete building, *194.
——Mounting oil circuit breakers on angle iron frame, *140.
——Reversing rotation of motor-driven machine, *398.
——Safety lighting-feeder switchboard, *91.
——Safety switches stop joy riding on industrial trucks, *396.
McKelway, G. H. Steel messenger wire supports cables in factory sub-station, 302.
Mills, A. S. Using structural steel in mounting motors on machines, *119.
Miller, John H. Care of electrical instruments, 92.
Millman, Walter H. Serviceable trolley and runway, *50.
Moler, C. C. Ordinary bell indicates condition of circuit, *139.

NAFZIGER, THOMAS. Chain eliminates troubles of belt drive on short centers, 350.
——Squirrel-cage motor used for regenerative braking on elevator, *596.

O'BRIEN, M. A. Compressed air driven paving breakers used to remove concrete wall, *546.
Oehlschlager, W. A. Alarm indicates when circuit breaker opens, *138.

PALMER, W. W. Flat welding electrode, *356.
Pearson, John W. Bar on portable lamp guard holds lamp in place, *497.
Phillips, Marin. Troubles in D. C. armatures, *435.
Pierce, C. G. How to cut mica right shape for insulating commutator clamping ring, *200.
Pollard, Leon L. Static electricity on belts, *448.
Practical Pete. Absorbing ideas is one thing—using them another, *57.
——Here's another one—and some more evidence of how long a good motor will stand up, *509.
——Hiring and firing, *105.
——If you believe this—practice it, *606.
——Introduces himself, *1.
——Letters, *136.
——Letters from readers, *86.
——Motor and starter troubles—diagnosis and remedies, 336.
——Photos of good and bad looking installations, *157.
——Question and answer department, shall we have a?, *190.
——The maintenance man, *209.
——There are ways and ways of doing things, *559.
——What suggestions can you offer as improvements on this installation?, *263.

RAKOSKE, J. B. Portable scaffold made from two ladders, *349.
Rich, H. S. Annunciator system for jig room in machine shop, 399.
——Changing pulley speed, *199.
——Copper shoes prevent rust forming on crane rails, *41.
——Crane feeder in conduit, 349.
——Platforms for suspending motors near ceiling, 9 *48.
——Porcelain tube cutters made from gas pliers, *48.
——Safety and economy in wiring the industrial plant, 352.
——Safety precautions when operating high tension switches, 141.
——Sloppy wiring job is eye sore, *243.
——Speed in drilling slate, 145.
——Substitutes for turnbuckles to tighten wires, *500.
——Supports for light and power wiring on angle irons *193.
——Suspending a thousand pound motor near the ceiling, *240.
——Template for drilling large holes in thin sheet steel, *354.
——Using belt drive near wall, *193.
——Wooden rack for storing spare pulleys, *304.
Rich, M. J. Inductive test for polarity of commutating poles, *96.
Roe, A. C. Changing a cross-over coil to one less liable to short circuit, *550.
——Changing a two-phase 2,200-volt generator to operate at three-phase 220 volts, *453.
——Coil-making methods, *337.
——Cutting out coils in D. C. windings, *384.
——Diagrams for coil winders' second information, *283.
——Laying out coils for D. C. armatures and A. C. stators, *159.
——Rack for small reels maintains proper tension on wire, *355.
——Re-winding two-phase motor for three-phase operation, 144.
——Rewinding universal motors, *568.
——Rewound motor for testing phase rotation, 93.
——Simple cell bender for forming slot insulation, *251.
——Special hand winding saves time in rewinding small armatures, *502.
——Special tools to pack wires in partly closed slots, *143.
——Split and layer windings for small armatures, *78.
——Testing field coils for short circuits, *549.
——Winding armature coils to insure thorough impregnation, 601.
——Winding fractional-horsepower D. C. motors, *7.
——Winding small motors, *481.
——Winding split-phase motors and locating trouble, *229.
——Wound rotor connections, *533.
Rolf, G. S. Coupling bent pipes in out-of-way places, 451.

ST. JOHN, H. M. Electric furnace as metal melting machine, *17, comment, 36.
Scott, Wirt S. Electric ovens are good investment, *275.
Seward, W. E. Heating of circuit breakers and cables by induction prevented, *243.
——Keeping switchboard frame from heating, *142.

Sherwood, H. B. Rubber-covered wire and conduit save cost in underground construction, *298.
Shute, J. M. Good foundry lighting, *165.
Smith, Charles E. Making cable clamp and tap-off from same castings, *195.
Smith, Norman B. Motors in steamy and wet places, *515.
Smith, W. B. Causes and methods of remedying ordinary bearing troubles, 196.
Snow, John E. Determining power of small motors, *499.
Soares, Eustace C. Board for testing two-phase, three phase, or direct-current motors, *97.
——Connecting auto-transformers in parallel with one secondary witch, *141.
——Crane trolley quickly repaired by brazing, *146.
——Plugging shafts of small armatures, *49.
——Remote control of motors on hoists, *90.
Spencer, B. K. Insurance protection from loss by breakdown of electrical equipment, *486.
Stalford, V. K. Switchboard construction combining safety and flexibility for extensions, *353.
Stanford, Ray C. Testing armatures for opens, shorts and grounds, *452.
Stafford, H. E. Ball thrust bearing reduces pump motor power consumption, *397.
——Induction motor troubles—diagnosis and remedies, 22.
——Metal motor housing protects against dust and gases, *395.
——Reconnecting motor to reduce speed from 1200 R.P.M. to 900 R.P.M., 400.
——Synchronous motor troubles, 217.
——Troubles of D. C. machines, 430.
Stevens, Roger B. Motor protection and control equipment of American Sugar Refining Co., *463.
Stewart, L. J. Handling equipment changes and maintenance of electrical and associated mechanical systems, *317.
Sweazey, Irving E. Emergency arrangement for uncoupling conduit, *39.

THOMAS, J. S. Localized blower improves working conditions, *199.
Tillman, Stephen. Rotor-soldering outfit made of pipe fittings, *146.
Todd, W. B. Acid-proof construction for conduit and lamps, *38.

VAN BRUNT, G. A. Installing fire pumps, *583.
——Ball and roller bearings, *420.
Vanderpoll, Jan A. Connection for starting motor when line voltage is often low, *545.

WADE, H. J. Testing contact of knife switch blades, 40.
Walker, C. Supporting conductors on steel members, *38.
Walsh, J. M. Circuit breaker alarm attachment tells when circuit is opened, *37.
——Inexpensive trimmer for cutting insulation in strips, *249.
——Instruments for maintenance work, *479.
——Poor brush contact seriously affected speed of direct-current motor, 200.
J.M. Walsh:—
——Lamp burnouts by high voltage prevented by balance control set, *41.
——Tension block that will not injure insulation on magnet wire, *197.
Wanamaker, E. Reasons for success of electric welding in shops of Rock Island lines, *172.
——Welding iron and steel, *218, comment, 238.
Weaver, Raymond H. Vertical cables held taut by turnbuckles, *192.
Wehmes, Ivan C. Coil winding machine made from old lathe, *549.
Weightman, H. E. Determining fuse size for mercury-arc rectifier, 192.
Westbrook, F. A. Lead-covered wire best for wet, salty atmosphere, 397.
——Supporting varnished-cambric-insulated risers in buildings, *351.
Whitcomb, Arthur J. Steel and tube mill inspection and maintenance, *23.
——Steel mill motor failures, *377.
——Trouble in reversing-roll electric drives, *63.
Wolf, Herbert J. Load survey shows whether proper size of motor is being used, 195.
Wood, L. E. Angle iron clamp for restacking laminations, *48.
——Block for insulating coils before placing in motor, *94.
——Inspection system which keeps 1,200 motors running, 546.
——Reducing costs of threading cotton sleeving on armature coils, *46.
Wotier, Arthur A. Ventilation in industrial works, 597.
Wright, D. Investigations of routine material handling in old plant preliminary to installing electric trucks, 455.